



Date: 07 February 2022

Reference: PCG NTM 028 - 2022
(HD 025/22)

Subject : NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 022/22 – BOHOL, W. AND N. COASTS – UNLIT BUOYS

THE FOLLOWING BUOYS WERE REPORTED UNLIT:

NAME OF BUOY	POSITION
TAG Channel Buoy	09° 39' 19"N., 123° 49' 51"E.
LPM-TU Buoy 7	10° 02' 28"N., 123° 55' 42"E.
LPM-M Buoy 5	09° 44' 09"N., 123° 50' 02"E.
LPM-U Buoy 7	10° 04' 26"N., 124° 28' 53"E.
LPM-TAP Buoy 1	10° 20' 39"N., 124° 00' 10"E.
LSM-TAP Buoy 6	10° 02' 53"N., 124° 32' 30"E.
LSM-TAP Buoy 8	10° 02' 57"N., 124° 32' 17"E.
LSM-TAP Buoy 10	10° 03' 11"N., 124° 32' 02"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE-MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

CAPTAIN ANTONIO G VALENZUELA JR
Officer-in-Charge, Hydrography Branch

Please e-mail maritime.affairs@namria.gov.ph if any part of this message is not received

NAMRIA OFFICES:

Lawton Avenue, Fort Bonifacio, 1634 Taguig City, PH ☎ (632) 8810-4831 to 41
421 Barraca St., San Nicolas, 1010 Manila, PH ☎ (632) 8241-3494 to 98



ISO 9001:2015
CERTIFIED FOR MAPPING
AND GEOSPATIAL
INFORMATION MANAGEMENT

INVESTORS IN PEOPLE™
We invest in people Silver