



PHILIPPINE NOTICES TO MARINERS

Edition No.: 05
31 May 2019

Notices Nos.: 024 to 036

CONTENTS

- I Index of Charts Affected
 - II Notices to Mariners
 - III Corrections to Nautical Publications
 - IV Navigational Warnings
 - V Publication Notices
-

Produced by the Hydrography Branch

Published by the
Department of Environment and Natural Resources
NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Notices to Mariners – Philippine edition are now on- line at
[http:// www.namria.gov.ph/download.php](http://www.namria.gov.ph/download.php)

Subscription may be requested thru e-mail at icsu_hd@namria.gov.ph

THE PHILIPPINE NOTICES TO MARINERS is the monthly publication produced by the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA). It contains the recent charts correction data, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained by sending a request through e-mail address: oss@namria.gov.ph or by downloading at the NAMRIA website: www.namria.gov.ph/download.php.

Masters of vessels and other concerned are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots which may come to their attention to the **Director, Hydrography Branch**. If such information warrants urgent attention like for instance the non-existence of aids to navigation or failure of light beacons or similar structure or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:

Mail: NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, 1010 Manila, Philippines

E-mail: maritime.affairs@namria.gov.ph

Fax: (+632) 242-2090


The Hydrographic Note form at the back cover page of this publication must be used in reporting information on dangers to navigation, lighted aids, and other features that should be included in the nautical charts.

Explanatory Notes

- The Philippine Notices to Mariners is divided to following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts which have been affected by Notices to Mariners and the notice numbers which have affected them.

Section II-A. Notices to Mariners - Contains corrections to nautical charts in sequential number with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:



Notice No. preceded by asterisk “ * ” indicates that the information is based upon original Philippine source.

Section II-B. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affects the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “preliminary” or “temporary”, respectively.

A list of Temporary and Preliminary Notices that are still in force, as well as those that are canceled, is published in this publication every month. The list may be read on page iv.

Section III-A. Corrections to List of Lights – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contains updates will be denoted by an asterisk “ * ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from true the North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should be forwarded to the Commandant of the Philippine Coast Guard.

Section III-B. Coast Pilot Corrections – Contains the corrections to the latest edition of the Philippine Coast Pilot book.

Section IV. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section V. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed specially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 31 May 2019)

- 05(036)P/19 – LUZON, W. COAST, Subic Bay – Buoy
- 04(023)P/19 – MINDANAO, N. COAST, Iligan Bay – Buoy
- 11(063)P/18 – LUZON, W. COAST, Subic Bay – Wreck
- 10(055)P/18 – LUZON, W. COAST, Manila Harbor – Wreck
- 06(033)P/18 – LUZON, W. COAST, San Fernando Harbor – Buoy
- 01(004)P/18 – SULU ARCHIPELAGO – Recommended Route
- 07(040)P/17 – MINDANAO, W. COAST, Moro Gulf – Recommended Route
- 02(014)P/17 – MINDANAO, N. COAST, Butuan Bay – Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected	1
Notices to Mariners	2
Temporary & Preliminary Notices	11
List of Lights Corrections	12
Coast Pilot Corrections	
Navigational Warnings	15
Publication Notices	25

I**INDEX OF CHARTS AFFECTED**

Chart No.	Notices Nos.		Chart No.	Notices Nos.
1501	05(26)19		4338	05(33)19
	05(36)P/19			
			4351	05(35)19
1502	05(36)P/19			
			4420	05(26)19
1535	05(29)19			
	05(32)19		4422	05(30)19
1543	05(28)19		4423	05(31)19
1551	05(35)19		4464	05(25)19
1552	05(35)19		4468	05(25)19
1564	05(26)19		4604	05(29)19
	05(27)19			05(32)19
	05(28)19			
			4639	05(32)19
4212	05(36)P/19			
			4640	05(29)19
4213	05(36)P/19			
			4706	05(26)19
4214	05(26)19			05(27)19
	05(27)19			05(30)19
				05(31)19
4218	05(28)19			05(33)19
	05(34)19			05(34)19
4226	05(34)19		4714	05(26)19
				05(27)19
4243	05(24)19			05(33)19
				05(34)19
4255	05(26)19			
			4715	05(34)19
4257	05(26)19			
			4719	05(30)19
4267	05(28)19			05(31)19
4273	05(34)19		4723A	05(26)19
				05(27)19
4305	05(27)19			05(33)19

II NOTICES TO MARINERS

05(024)19 – LUZON, W. COAST, Manila Bay – Landmark

Chart 4243 4Ed 05/2016 [WGS-84 Datum] Last NM 01(001)19

Move  SAN ROQUE
(spire) from: 14° 28.40' N., 120° 53.39' E.
to: 14° 28.82' N., 120° 54.06' E.

(US Survey Report; HD 011/19)

*05(025)19 – LEYTE, E. COAST, San Juanico Strait – Light

Chart 4420 2Ed 09/30/1974 Rev 11/12/1979 [Luzon Datum] Last NM 08(043)18

Amend characteristics of San Juanico Bridge #2 Center Light from: Fl.G.3s5M to: Fl.R.3s5M
at: 11° 18.06' N., 124° 58.12' E.

Chart 4464 1Ed 01/06/1969 Rev 07/27/1981 [Luzon Datum] Last NM 08(043)18

Amend characteristics of San Juanico Bridge #2 Center Light from: Fl.G.3s5M to: Fl.R.3s5M
at: 11° 18.06' N., 124° 58.12' E.

Chart 4468 1Ed 08/05/1957 Rev 02/28/1980 [Luzon Datum] Last NM 11(066)17

Amend characteristics of San Juanico Bridge #2 Center Light from: Fl.G.3s5M to: Fl.R.3s5M
at: 11° 18.06' N., 124° 58.12' E.

(PCG NM No. 100 of 2019 & 104 of 2019; HD 099/19 & 107/19)

*05(026)19 – LUZON, W. COAST, Nasugbu Bay – Light. Airport

Chart 1501 1Ed 02/02/2012 [WGS-84 Datum] Last NM 04(021)19

Insert  Fl.5s at: 14° 04.93' N., 120° 37.22' E.

Delete  Fl.G.5s7M at: 14° 05.01' N., 120° 37.15' E.



at: 14° 04.68' N., 120° 38.00' E.

II NOTICES TO MARINERS

*05(026)19 – LUZON, W. COAST, Nasugbu Bay – Light. Airport. (continued)

Chart 1564 1Ed 02/02/2012 [WGS-84 Datum] Last NM 11(060)18

Insert  Fl.5s at: 14° 04.93' N., 120° 37.22' E.

Delete  Fl.G.5s7M at: 14° 04.98' N., 120° 37.35' E.



at: 14° 04.68' N., 120° 38.00' E.

Chart 4214 2Ed 12/02/1991 [Luzon Datum] Last NM 04(021)19

Insert  Fl.5s at: 14° 05.02' N., 120° 37.14' E.

Delete  Fl.G.5s7M at: 14° 05.10' N., 120° 37.07' E.

Chart 4255 2Ed 01/06/1975 Rev 06/17/1985 [Luzon Datum] Last NM 04(021)19

Insert  Fl.5s at: 14° 05.02' N., 120° 37.14' E.

Delete  Fl.G.5s7M at: 14° 05.10' N., 120° 37.07' E.

Chart 4257 1Ed 01/09/1956 Rev 01/12/1981 [Luzon Datum] Last NM 04(021)19

Insert  Fl.5s at: 14° 05.02' N., 120° 37.14' E.

Delete  Fl.G.5s7M at: 14° 05.10' N., 120° 37.07' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 04(021)19

Amend characteristics of Nasugbu Light from: Fl.G.5s7M to: Fl.5s
at: 14° 04.9' N., 120° 37.2' E.

Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 04(021)19

Amend characteristics of Nasugbu Light from: Fl.G.5s7M to: Fl.5s
at: 14° 05.0' N., 120° 37.1' E.

Chart 4723A 2Ed 12/22/2018 [WGS-84 Datum] Last NM 04(020)19

Amend characteristics of Nasugbu Light from: Fl.G.5s7M to: Fl.5s
at: 14° 04.9' N., 120° 37.2' E.

(NAMRIA Survey Report; HD 129/19)

II NOTICES TO MARINERS

*05(027)19 – MINDORO, N. COAST, Ilog Anchorage – Light.

Chart 1564 1Ed 02/02/2012 [WGS-84 Datum] Last NM 05(026)19

Insert  ☆ Fl.5s15M at: 13° 28.00' N., 120° 46.30' E.

Delete  ☆ Fl.5s12M at: 13° 27.81' N., 120° 44.99' E.

Chart 4214 2Ed 12/02/1991 [Luzon Datum] Last NM 05(026)19

Insert  ☆ Fl.5s15M at: 13° 28.09' N., 120° 46.22' E.

Delete  ☆ Fl.5s12M at: 13° 27.90' N., 120° 44.90' E.

Chart 4305 2Ed 12/07/1992 [Luzon Datum] Last NM 08(052)17

Insert  ☆ Fl.5s15M at: 13° 28.09' N., 120° 46.22' E.

Delete  ☆ Fl.5s12M at: 13° 27.90' N., 120° 44.90' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 05(026)19

Insert  ☆ Fl.5s15M at: 13° 28.0' N., 120° 46.3' E.

Delete  ☆ Fl.5s12M at: 13° 27.8' N., 120° 45.0' E.

Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 05(026)19

Insert  ☆ Fl.5s15M at: 13° 28.1' N., 120° 46.2' E.

Delete  ☆ Fl.5s12M at: 13° 27.9' N., 120° 44.9' E.

Chart 4723A 2Ed 12/22/2018 [WGS-84 Datum] Last NM 05(026)19

Insert  ☆ Fl.5s15M at: 13° 28.0' N., 120° 46.3' E.

Delete  ☆ Fl.5s12M at: 13° 27.8' N., 120° 45.0' E.

(NAMRIA BRPH Ventura; HD 121/19)

II NOTICES TO MARINERS

***05(030)19 – SAMAR, E. COAST, Port Borongan – Light.**

Chart 4422 1Ed 10/16/1917 Rev 06/21/1976 [Luzon Datum] Last NM 05(120)16

Amend characteristics of Divinubo Island Light from: Fl.10s41m11M to: Fl.5s41m11M
at: 11° 35.92' N., 125° 30.17' E.

Chart 4422 – Port Borongan inset

Amend characteristics of Divinubo Island Light from: Fl.10s41m11M to: Fl.5s41m11M
at: 11° 35.92' N., 125° 30.17' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 05(027)19

Amend characteristics of Divinubo Island Light from: Fl.10s41m11M to: Fl.5s41m11M
at: 11° 35.8' N., 125° 30.3' E.

Chart 4719 1Ed 07/24/1961 Rev 02/12/1985 [Luzon Datum] Last NM 04(019)19

Amend characteristics of Divinubo Island Light from: Fl.10s41m11M to: Fl.5s41m11M
at: 11° 35.9' N., 125° 30.2' E.

(PCG NM No. 104 of 2019; HD 107/19)

***05(031)19 – SAMAR, S. COAST, Leyte Gulf, Maglolobo Bay – Light.**

Chart 4423 1Ed 10/29/1956 Rev 04/21/1986 [Luzon Datum] Last NM 11(063)17

Insert  Fl.10s at: 11° 06.20' N., 125° 22.10' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 05(030)19

Insert  Fl.10s at: 11° 06.1' N., 125° 22.2' E.

Chart 4719 1Ed 07/24/1961 Rev 02/12/1985 [Luzon Datum] Last NM 05(030)19

Insert  Fl.10s at: 11° 06.2' N., 125° 22.1' E.

(PCG NM No. 104 of 2019; HD 107/19)

II NOTICES TO MARINERS

***05(032)19 – MINDANAO, N. COAST, Inamucan Bay – Buoy.**

Chart 1535 1Ed 02/02/2012 [WGS-84 Datum] Last NM 05(029)19

Insert  $Fl(2)G.5s$
"1" at: 08° 36.81' N., 123° 43.96' E.

Chart 4604 1 Ed 04/30/1956 Rev 01/07/1985 [Luzon Datum] Last NM 05(029)19

Insert  $Fl(2)G.5s$
"1" at: 08° 36.89' N., 123° 43.88' E.

Chart 4639 1Ed 10/30/1961 Rev 07/08/1985 [Luzon Datum] Last NM 06(024)18

Insert  $Fl(2)G.5s$
"1" at: 08° 36' 53.3"N., 123° 43' 52.5"E.

(PCG NM No. 093 of 2019; HD 088/19)

***05(033)19 – MINDORO, NE. COAST, Lubang Islands – Light.**

Chart 4338 1Ed 10/17/1959 Rev 01/05/1976 [Luzon Datum] Last NM 07(165)16

Amend characteristics of Cabra Light from: $Fl(2)10s66m22M$ to: $Fl.10s66m22M$
at: 13° 53.40' N., 120° 01.32' E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 05(031)19

Amend characteristics of Cabra Light from: $Fl(2)10s66m22M$ to: $Fl.10s66m22M$
at: 13° 53.3' N., 120° 01.4' E.

Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 05(027)19

Amend characteristics of Cabra Light from: $Fl(2)10s66m22M$ to: $Fl.10s66m22M$
at: 13° 53.4' N., 120° 01.3' E.

Chart 4723A 2Ed 12/22/2018 [WGS-84 Datum] Last NM 05(027)19

Amend characteristics of Cabra Light from: $Fl(2)10s66m22M$ to: $Fl.10s66m22M$
at: 13° 53.3' N., 120° 01.4' E.

(PCG NM No. 126 of 2019; HD 132/19)

II NOTICES TO MARINERS

***05(034)19 – LUZON, E. COAST, Silangan Pass – Light.**

Chart 4218 1Ed 03/1958 Rev 09/15/1986 [Luzon Datum] Last NM 05(028)19

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59.90' N., 122° 10.92' E.

Chart 4226 1Ed 08/14/1961 Rev 01/22/1979 [Luzon Datum] Last NM 03(010)19

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59.90' N., 122° 10.92' E.

Chart 4273 1Ed 08/07/1967 Rev 03/12/1984 [Luzon Datum] Last NM 07(121)15

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59' 54"N., 122° 10' 55"E.

Chart 4706 2Ed 12/2010 [WGS-84 Datum] Last NM 05(033)19

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59.8' N., 122° 11.0' E.

Chart 4714 1Ed 09/14/1959 Rev 03/31/1986 [Luzon Datum] Last NM 05(033)19

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59.9' N., 122° 10.9' E.

Chart 4715 1Ed 12/1958 Rev 07/1975 [Luzon Datum] Last NM 04(016)19

Amend characteristics of Silangan Pass Light from: Fl(2)5s9m18M to: Fl.5s9m18M
at: 13° 59.9' N., 122° 10.9' E.

(PCG NM No. 127 of 2019; HD 139/19)

II NOTICES TO MARINERS

***05(035)19 – CALAMIAN GROUP, Coron Bay – Light. Landmark.**

Chart 1551 1Ed 02/29/2012 [WGS-84 Datum] Last NM 02(033)16

Move  Fl.5s from: 11° 58.95' N., 120° 13.49' E.
to: 11° 58.97' N., 120° 13.49' E.

Chart 1552 1Ed 02/29/2012 [WGS-84 Datum] Last NM 10(248)15

Move  Fl.5s from: 11° 58.95' N., 120° 13.49' E.
to: 11° 58.97' N., 120° 13.49' E.

Chart 4351 2Ed 11/04/1994 [Luzon Datum] Last NM 09(056)17

Move  Fl.5s from: 11° 59.03' N., 120° 13.40' E.
to: 11° 59.05' N., 120° 13.40' E.

(NAMRIA Survey Report; HD 140/19)

II TEMPORARY & PRELIMINARY NOTICES

*05(036)P/19 – LUZON, W. COAST, Subic Bay – Buoy

1. Insert buoys with the following details:

	Position (WGS-84 Datum)	Light Characteristics
SBMA-A	14° 46' 48.00"N., 120° 12' 48.54"E.	Iso W 2s
SBMA-3	14° 46' 58.26"N., 120° 12' 26.28"E.	Fl(2)G 4s
SBMA-5	14° 46' 30.96"N., 120° 14' 13.26"E.	Fl G 4s
SBMA-10	14° 47' 58.86"N., 120° 14' 44.22"E.	Fl(2)R 4s
SBMA-12	14° 48' 29.76"N., 120° 15' 34.38"E.	Fl R 4s
SBMA-B	14° 48' 43.08"N., 120° 15' 00.48"E.	Iso W 2s

Charts affected: 1501, 1502, 4212, and 4213
(PCG NM No. 117 of 2019; HD 129/19)

III

LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)	
REGION II – CAGAYAN VALLEY								
BATANES								
0000	F2823	YÁMI	21 07 04 N 121 56 51 E	FI W 5s	20	15	White metal post *	Vis 200°-310°(110°) In WGS-84 Datum *
REGION III – CENTRAL LUZON								
ZAMBALES								
	SBMA-A		14 46 48 N 120 12 49 E	Iso W 2s				Safe Water Mark. MMSI No. 995481335. In WGS-84 Datum *
	*		*	*				
	SBMA-3		14 46 58 N 120 12 26 E	FI(2)G 4s				Port Hand Mark. MMSI No. 995481331. In WGS-84 Datum *
	*		*	*				
	SBMA-5		14 46 31 N 120 14 13 E	FI G 4s				Port Hand Mark. MMSI No. 995481333. In WGS-84 Datum *
	*		*	*				
	SBMA-10		14 47 59 N 120 14 44 E	FI(2)R 4s				Starboard Hand Mark. MMSI No. 995481332. In WGS-84 Datum *
	*		*	*				
	SBMA-12		14 48 30 N 120 15 34 E	FI R 4s				Starboard Hand Mark. MMSI No. 995481334. In WGS-84 Datum *
	*		*	*				
	SBMA-B		14 48 43 N 120 15 00 E	Iso W 2s				Safe Water Mark. MMSI No. 995481336. In WGS-84 Datum *
	*		*	*				
REGION IV-A - CALABARZON								
BATANGAS								
0063	F2626	NASUGBU	14 04 56 N 120 37 13 E	FI W 5s			White concrete tower	In WGS-84 Datum
			*	*		*	*	*
0067	F2606.6	MAINAGA	13 45 47 N 120 57 16 E	FI G 5s	25	7	Concrete beacon, 3	*

Note: Asterisk “ * ” indicates new information in the column above it.

III

LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)	
REGION IV-A - CALABARZON QUEZON								
0120	F2760	SILANGAN PASS	13 59 49 N 122 11 00 E	FI W 5s	9	18	White concrete tower	Vis 038°-100°(62°). Vis 205°-271°(66°). In WGS-84 Datum *
		*	*				*	
REGION IV-B – MIMAROPA MINDORO OCCIDENTAL								
0146	F2620	CABRA	13 53 19 N 120 01 24 E	FI W 10s	66	22	Concrete, white square brick tower on dwelling, 20	Vis 320°-253°(293°). In WGS-84 Datum *
		*	*				*	
0150	F2566	WAWA (Abra de Ilog)	13 28 00 N 120 46 18 E	FI W 5s		15	Concrete tower, 21	In WGS-84 Datum *
	*		*			*	*	
PALAWAN								
0559	F2179.2	CORON	13 58 58 N 120 13 30 E	FI W 5s			White GRP tower	In WGS-84 Datum *
		*	*				*	
REGION VIII – EASTERN VISAYAS EASTERN SAMAR								
0294	F2450	DIVINUBO ISLAND	11 35 51 N 125 30 15 E	FI W 5s	41	11	Concrete, white framework tower on house, 14	Vis 172°-335°(163°). In WGS-84 Datum *
		*	*				*	
0852		BALANGIGA	11 06 08 N 125 22 11 E	FI W 10s				In WGS-84 Datum *
*	*	*	*	*			*	
LEYTE								
0573	F2423.2	SAN JUANICO BRIDGE #2 CENTER (NORTH)	11 17 59 N 124 58 12 E	FI R 3s		5	Bridge	In WGS-84 Datum *
		*	*				*	
REGION X – NORTHERN MINDANAO MISAMIS OCCIDENTAL								
		<i>O-SHM 10</i>	08 08 29 N 123 51 33 E	FI(2)R 5s			Red. Topmark: single red cone pointing upward	Lateral Starboard Hand Mark. MMSI No. 995481278. In WGS-84 Datum *
		*	*	*			*	
		<i>O-ECM 18</i>	08 07 40 N 123 50 05 E	FI(3)W 10s			Black with horizontal yellow band. Topmark: top cone pointing upward and bottom cone pointing downward.	East Cardinal Mark. MMSI No. 9954581286. In WGS-84 Datum *
		*	*	*			*	

Note: Asterisk “*” indicates new information in the column above it.

III

LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
REGION X – NORTHERN MINDANAO							
MISAMIS OCCIDENTAL							
	<i>PI-PHM 1</i>	08 36 49 N 123 43 57 E	Fl(2)G 5s			Green. Topmark: single green cylinder	Lateral Port Hand Mark. MMSI No. 995481297. In WGS-84 Datum TE 2019
	*	*	*			*	*

Note: Asterisk “ * ” indicates new information in the column above it.

V

NAVIGATIONAL WARNINGS

Date: 23 March 2018

Reference: PCG NTM 062-2018 (HD 055/18)

MESSAGE

NAVPHIL 036/18 – LUZON, W. COAST, PASIG RIVER – CONSTRUCTION WORKS

DUMDUMA CONSTRUCTION AND TRADING CORP. IS CONSTRUCTING THE SAN JUAN RIVER VIADUCT FROM 05 MARCH 2018 TO 31 DECEMBER 2019 WITHIN THE VICINITY OF THE FOLLOWING COORDINATES:

14° 35' 26.63"N., 121° 00' 49.67"E.

14° 35' 23.39"N., 121° 00' 50.40"E.

14° 35' 23.15"N., 121° 00' 51.12"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 08 November 2018

Reference: PCG NTM 258-2018 (HD 288/18)

MESSAGE

NAVPHIL 173/18 – LUZON, W. COAST, PASIG RIVER – REHABILITATION

NAPINDAN HYDRAULIC CONTROL SYSTEM IS BEING REHABILITATED FROM 05 NOVEMBER 2018 TO 11 MARCH 2022 WITHIN THE VICINITY OF THE FOLLOWING COORDINATES:

14° 33' 28"N., 121° 04' 06"E.

14° 33' 26"N., 121° 04' 10"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 12 March 2019

Reference: PCG NTM 059-2019 (HD 056/19)

MESSAGE

NAVPHIL 026/19 – LUZON, W. COAST, PASIG RIVER – BRIDGE CONSTRUCTION

THE CHINA ROAD AND BRIDGE CORPORATION AND THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAY (DPWH) HAD AN ON-GOING BRIDGE CONSTRUCTION PROJECT ON DATES AND PLACES AS INDICATED:

- A. VICINITY OF BINONDO – INTRAMUROS MANILA ALONG PASIG RIVER MARCH 2019 TO DECEMBER 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 14° 35' 45.22"N., 120° 58' 30.15"E.
POINT B: 14° 35' 45.20"N., 120° 58' 28.35"E.
POINT C: 14° 35' 41.20"N., 120° 58' 28.78"E.
POINT D: 14° 35' 41.41"N., 120° 58' 30.28"E.

- B. VICINITY OF MANDALUYONG AND MAKATI ESTRELLA – PANTALEON BRIDGE ALONG PASIG RIVER MARCH 2019 TO DECEMBER 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 14° 34' 03.23"N., 121° 02' 11.40"E.
POINT B: 14° 34' 01.60"N., 121° 02' 12.01"E.
POINT C: 14° 34' 02.56"N., 121° 02' 18.77"E.
POINT D: 14° 34' 04.65"N., 121° 02' 18.44"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 10 April 2019

Reference: PCG NTM 086-2019 (HD 085/19)

MESSAGE

NAVPHIL 037/19 – LUZON, W. COAST, MANILA BAY – MARITIME ACTIVITY

SANDS MINING AND DEVELOPMENT IS CONDUCTING MARINE SEDIMENT SURVEY AND EXPLORATORY DRILLING IN OFFSHORE AREA OF TANZA AND NAIC, CAVITE FROM 01 APRIL 2019 TO 30 JUNE 2019 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

- A: 14° 21' 57"N., 120° 40' 30"E.**
- B: 14° 23' 50"N., 120° 42' 00"E.**
- C: 14° 23' 50"N., 120° 43' 37"E.**
- D: 14° 21' 57"N., 120° 42' 00"E.**

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 11 April 2019

Reference: NOTAM 091-2019 (HD 087/19)

MESSAGE

NAVPHIL 039/19 – LUZON W. COAST, PALAWAN– OFFSHORE ACTIVITY

THE PHILODRILL CORPORATION CONTRACTED EASTERN NAVIGATION PTE. LTD USING M.V. ENA HABITAT IS CONDUCTING WELL PLUG AND ABANDON CAMPAIGN FOR TWO (2) MONTHS STARTING 05 APRIL 2019 AT THE FOLLOWING POSITIONS:

POINT 1	11° 28' 46.90" N, 119° 01' 18.17" E.
POINT 2	11° 02' 19.90" N, 118° 49' 57.40" E.
POINT 3	11° 02' 18.90" N, 118° 49' 57.50" E.
POINT 4	11° 01' 54.96" N, 118° 47' 37.62" E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE-MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

IV

NAVIGATIONAL WARNINGS

Date: 24 April 2019

Reference: Philippine News Agency (HD 102/19)

MESSAGE

NAVPHIL 044/19 – LUZON W. COAST, MANILA BAY– DREDGING

THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS IS CONDUCTING DREDGING WORKS AT APPROXIMATELY 1.5 KILOMETER STRETCH OF MANILA BAY FROM THE MANILA YACHT CLUB BREAKWATER TO THE UNITED STATES EMBASSY UNTIL 31 JULY 2019 IN THE AREA BOUNDED BY:

POINT 1	14° 33' 50.55" N, 120° 59' 05.12" E.
POINT 2	14° 33' 48.35" N, 120° 59' 00.78" E.
POINT 3	14° 34' 32.83" N, 120° 58' 37.64" E.
POINT 4	14° 34' 30.64" N, 120° 58' 46.12" E.

HEAVY EQUIPMENT COMPOSED OF AMPHIBIOUS EXCAVATORS, DUMPING SCOWS, DUMP TRUCKS, DEBRIS SEGREGATOR, STREET SWEEPERS AND VACUUM SEWER JET CLEANERS ARE DEPLOYED IN THE AREA AND STRATEGIC LOCATIONS.

THIS CANCELS NAVPHIL 022/19.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE-MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

IV

NAVIGATIONAL WARNINGS

Date: 10 May 2019

Reference: NAMRIA (HD 117/19)

MESSAGE

NAVPHIL 049/19 – LUZON W. COAST, LINGAYEN GULF – HYDROGRAPHIC SURVEY

THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, UTILIZING A SURVEY SKIFF IS CONDUCTING HYDROGRAPHIC SURVEY ACTIVITIES AT LINGAYEN GULF, PANGASINAN FROM 09 MAY TO 20 JUNE 2019 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

- A: 16° 09' 06"N., 120° 04' 12"E.**
- B: 16° 09' 06"N., 120° 09' 00"E.**
- C: 16° 01' 30"N., 120° 09' 00"E.**
- D: 16° 01' 30"N., 120° 04' 12"E.**

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 14 May 2019

Reference: PCG NTM 118-2019 (HD 120/19)

MESSAGE

NAVPHIL 051/19 – LUZON, W. COAST, PASIG RIVER – DRILLING WORKS

SOIL PHILIPPINES INDEX TESTING INC. (SPITI) IS CONDUCTING A GEOTECHNICAL INVESTIGATION AND DRILLING WORKS AT PASIG RIVER FROM 06 MAY TO 15 JUNE 2019, AT THE FOLLOWING POSITION:

14° 33' 54.75"N., 121° 03' 29.70"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV

NAVIGATIONAL WARNINGS

Date: 16 May 2019

Reference: PCG NTM 122 & 123-2019 (HD 124 & 125/19)

MESSAGE

NAVPHIL 055/19 – PHILIPPINE WATERS – GUNNERY

THE PHILIPPINE NAVY (PN) WILL CONDUCT TEST FIRING OF THEIR NAVAL GUNS ON DATES AND PLACES AS INDICATED:

- C. BRP LEOVIGILDO GANTIOQUI (PC384) AT VICINITY 8.7 NAUTICAL MILES EAST OFF MATANAL POINT, BASILAN ON 07 JUNE 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 06° 38' 45.42"N., 122° 28' 46.98"E.
POINT B: 06° 33' 36.54"N., 122° 28' 50.22"E.
POINT C: 06° 33' 38.16"N., 122° 33' 54.24"E.
POINT D: 06° 38' 43.80"N., 122° 33' 57.54"E.

- D. BRP MANUEL GOMEZ (PB340) AT VICINITY 7.5 NAUTICAL MILES NORTHWEST OFF PORO POINT, SAN FERNANDO, LA UNION ON 05 TO 06 JUNE 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 16° 50' 32.16"N., 120° 02' 30.54"E.
POINT B: 16° 42' 40.68"N., 120° 01' 55.68"E.
POINT C: 16° 41' 18.84"N., 120° 10' 08.70"E.
POINT D: 16° 49' 17.04"N., 120° 10' 36.90"E.

- E. BRP EMILIO LIWANAG (PC118) AT VICINITY 18 NAUTICAL MILES SOUTHWEST OFF BALUT ISLAND, DAVAO OCCIDENTAL ON 11 TO 12 JUNE 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 05° 24.00'N., 124° 55.00'E.
POINT B: 05° 24.00'N., 125° 10.00'E.
POINT C: 05° 08.00'N., 125° 10.00'E.
POINT D: 05° 08.00'N., 124° 55.00'E.

- F. BRP ALFREDO PECKSON (PC32) AT VICINITY 3.5 NAUTICAL MILES SOUTH OFF CAMOTES ISLAND, CEBU ON 20 TO 21 JUNE 2019 IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:**

POINT A: 10° 32.00'N., 124° 15.00'E.
POINT B: 10° 32.00'N., 124° 25.00'E.
POINT C: 10° 22.80'N., 124° 35.00'E.
POINT D: 10° 22.00'N., 124° 15.00'E.

IV

NAVIGATIONAL WARNINGS

Date: 20 May 2019

Reference: NAMRIA (HD 136/19)

MESSAGE

NAVPHIL 061/19 – MINDORO N.W. Coast, LUBANG ISLAND – HYDROGRAPHIC SURVEY

THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, UTILIZING MOTOR BOAT SURVEY (MBS – 3) WILL CONDUCT HYDROGRAPHIC SURVEY ACTIVITIES AT TILIK, LUBANG, OCCIDENTAL MINDORO STARTING 31 MAY 2019 WITH A DURATION OF ONE AND ONE HALF (1 1/2) MONTH WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

**A: 13° 51' 33"N., 120° 10' 03"E.
B: 13° 51' 33"N., 120° 14' 37"E.
C: 13° 48' 31"N., 120° 14' 37"E.
D: 13° 48' 31"N., 120° 10' 03"E.**

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

V

PUBLICATION NOTICES

1. Newly Published Nautical Charts

- a. Chart 1510 – Lobod Point to Dijohan Point
1st Edition, 30 May 2019

- b. Chart 1520 – Siargao Island to Arangasa Island
1st Edition, 30 May 2019

Call the NAMRIA Map Sales Office (MSO) – Manila Branch at telephone numbers (+632) 245-9498 and (+632) 241-3494 local 117 for details regarding the purchase of the abovementioned publications.

- 2. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on nautical charts and nautical publications issued by this office especially if this affect navigational safety on Philippine Waters. Reported information may be sent using the Hydrographic Note or the Hydrographic Note for Port Information, which are on the succeeding pages.**

Reports may be sent through the following means:

Mail: NAMRIA – Hydrography Branch, 421 Barraca St., San Nicolas, Manila 1010
Email: maritime.affairs@namria.gov.ph and maritime.concerns@gmail.com
Fax: (+632) 242-2955

HYDROGRAPHIC NOTE

Date _____

Ref. No. _____

Name of ship or sender _____ IMO No. _____

Address of sender _____

Telephone/Mobile No. _____ E-mail _____

Subject _____

General locality _____

Position: Latitude. _____ Longitude. _____

Position fixing system used _____ Datum _____

Charts affected _____ Edition _____

ENCs affected _____

Latest Notice to Mariners held _____

Nautical Publications affected (Edition No.) _____

Details of anomaly or observation:

A replacement copy of Chart No. _____
is required (see Instruction 4).

Signature of observer/reporter _____

Tick box if not willing to be named as source of this information

INSTRUCTIONS

1. Mariners are requested to notify the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA) when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications that are seen to be necessary. Mariners can also report any ENC display issues experienced.
2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed, closely, whenever appropriate. Copies of this form may be obtained gratis from the Hydrography Branch at 421 Barraca St., San Nicolas, Manila, or by requesting thru email at maritime.affairs@namria.gov.ph.
3. **Position:** When a position is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar should be quoted. However, when there is a series of fixes along a ship's course, only the method of fixing and the objects used need to be indicated. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum used should be given.
4. **Paper Charts:** A cutting from the largest scale paper chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than the chart itself) these should be in red as above, but adequate detail from the chart must be traced in black ink to enable the amendments to be fitted correctly.

Electronic Navigational Charts (ENCs): A screen grab of the largest scale usage band ENC with the alterations and additions being shown thereon in red.

5. **Soundings:** When soundings are obtained, it is important to ensure that full details of the method of collection are included in this report. This include nut no limited to:
 - a. Make, model, and type of echo sounder used.
 - b. Whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given.
 - c. Time, date and time zone should be given in order that corrections for the height of the tide may be made where necessary, or a statement made as to what corrections for tide have already been made.
 - d. Where larger amounts of bathymetric data have been gathered, only those areas where a significant difference to the current chart or ENC should be specifically mentioned on the H102. The full data set may also be sent in, with an additional note added to this effect. If no significant differences are noted, the bathymetric data may still be of use, and sent in accordingly. Where full

data sets are included, a note as to the data owner and their willingness for the data to be incorporated into charts and ENC's included.

6. **For Echo Sounders that use electronic 'range gating'**, care should be taken that the correct range scale and appropriate gate width are in use. Older electro-mechanical echo sounders frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus, with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognized by the following:
 - a. the trace being weaker than normal for the depth recorded;
 - b. the trace passing through the transmission line;
 - c. the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from charted depths.

7. **Reports which cannot be confirmed or are lacking in certain details should not be withheld.** Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.
8. Changes to Port Information should be forwarded using Hydrographic Note for Port Information. Where there is insufficient space on the forms additional sheets should be used.
9. Reports using this form and relevant data should be sent either through mail at NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, Manila or through email at maritime.affairs@namria.gov.com and maritime.concerns@gmail.com.

An acknowledgement or receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course; for these purposes, the NAMRIA-Hydrography Branch may make reproductions of any material supplied. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received from other authorities or the sender states that they do not want to be named by using the appropriate tick box on the form. An explanation of the use made of contributions from all parts of the world would be too great a task and a further communication should only be expected when the information is of outstanding value or has unusual features.

HYDROGRAPHIC NOTE FOR PORT INFORMATION

Date: _____

Name of Observer/Reporter: _____ IMO No. _____

Address of sender _____

Telephone/Mobile No. _____ E-mail _____

Name of Port			
Approximate Position	Latitude		Longitude
Port Authority Name and contact details			
General Remarks Principal activities and trade. Latest population figures and date. Number of ships or tonnage handled per year. Maximum size of vessel handled. Copy of Port Handbook (<i>if available</i>).			
Berthing Facility Type (L-pier, T-pier, wharf, etc.) Names, numbers or positions & lengths. Depths alongside.			
Storage Facility Area of open storage area and warehouse Existence of reefer facilities, cold storage, and special storage facilities.			
Anchorage Position, designation, depths, holding ground, shelter afforded.			

<p>Pilotage Authority for requests.</p> <p>Pilot boarding position.</p> <p>Regulations (compulsory or not).</p> <p>Name of pilot association and contact details.</p>	
<p>Tugs Number available.</p> <p>Name of tug operator and contact details</p>	
<p>Directions Entry and berthing information.</p> <p>Tidal streams.</p> <p>Navigational aids.</p>	
<p>Small Craft Facility Name of yacht club, contact no., email address.</p>	
<p>Cargo Handling Containers, lighters, Ro-Ro etc.</p>	
<p>Repairs Hull, machinery and underwater.</p> <p>Shipyards.</p> <p>Docking or slipping facilities. <i>(Give size of vessels handled or dimensions)</i></p> <p>Divers.</p>	
<p>Rescue and Distress Salvage, Lifeboat, Coastguard, etc.</p> <p>Name of nearest Coast Guard station and contact details.</p>	
<p>Supplies Fuel. (with type, quantities and methods of delivery)</p> <p>Fresh water. (with method of delivery and rate of supply)</p> <p>Provisions.</p>	

<p>Services Medical.</p> <p>Ship Sanitation.</p> <p>Garbage and slops.</p> <p>Ship chandlery, tank cleaning, compass adjustment, hull painting.</p>	
<p>Communications Nearest airport or airfield.</p> <p>Port radio and information service. (with frequencies and hours of operating)</p>	
<p>Government Services Customs</p> <p>Quarantine</p> <p>Plant and Animal Quarantine</p> <p>Immigration</p>	
<p>Local Situation Health facilities (nearest hospitals, clinics, health centers)</p> <p>Banks and money remittance facilities</p>	
<p>Views Photographs (where permitted) of the approaches, leading marks, the entrance to the harbor etc.</p>	
<p>Additional Details</p>	

Signature of observer/reporter _____

Notes:

1. This form lists the information required for Philippine Coast Pilot and has been designed to help the sender and the recipient. The sections should be used as an aide-memoir, being used or followed closely, whenever appropriate. Where there is insufficient space on the form an additional sheet should be used.
2. **Reports which cannot be confirmed or are lacking in certain details should not be withheld.** Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.

Nautical Charts, Topographic Maps, Tide and Current Tables and related publications are available for sale at the following NAMRIA Map Sales Offices (MSO):

METRO MANILA:

NAMRIA Main Office MSO

Fort Andres Bonifacio, Taguig City
Contact Nos. (02) 810-4831 to 42 local 431,
(02) 810-5467

Manila MSO

Hydrography Branch
421 Barraca Street, San Nicolas, Manila
Contact Nos. (02) 241-3494 to 96 local 117,
(02) 245-9498

DENR Central Office MSO

Forest Management Bureau (FMB) Compound
Visayas Avenue, Quezon City
Contact Nos. (02) 925-1157

REGION I:

San Fernando (La Union) MSO

DENR Government Center
Sevilla, San Fernando City
Contact Nos. (0999) 405-6917

REGION II:

Cagayan MSO

DENR – LEP, Building II
Carig, Tuguegarao City
Contact Nos. (0999) 309-3702

CORDILLERA ADMINISTRATIVE REGION:

Baguio City MSO

Cottage I Forester Compound,
PACDAL, Baguio City
Contact Nos. (074) 442-5429, (074) 442-4531,
0918-9203590

REGION III:

Nueva Ecija MSO

GIS Room, WMRC Building,
Central Luzon State University Compound
Maharlika Highway, Muñoz City
Contact Nos. (044) 456-0690, 0917-9313827

Pampanga MSO

Diosdado Macapagal Government Center
Maimpis, San Fernando City
Contact Nos. (0910) 372-5623

REGION IV-A:

Southern Tagalog MSO

Provincial Planning and Development Office
Laurel Park, Capitol Site, Batangas City
Contact Nos. (0905) 506-8681

REGION IV-B:

Puerto Princesa MSO

DENR-PENRO Compound,
Brgy. Santa Monica, Puerto Princesa City
Contact Nos. (048) 433-1391, (0918) 283-7045

REGION V:

Legazpi City MSO

DENR-Operation/Survey Division,
Rizal St., Sagpon, Legazpi City
Contact Nos. (052) 480-9825, (0920) 437-8877

REGION VI:

Iloilo City MSO

Manuel Lagunilla Bldg,
DENR Compound, Parola, Iloilo City
Contact Nos. (0919) 887-3862,

REGION VII:

Cebu City MSO

Room 301, Osmeña Bldg. II, Osmeña Blvd, Cebu City
Contact Nos. (032) 505-9945, (0922) 791-0372

REGION VIII:

Tacloban City MSO

DENR Compound, Sto. Niño Extension, Tacloban City
Contact Nos. (053) 325-6223, (053) 321-3386,
0921-3628489

REGION IX:

Zamboanga City MSO

DENR CENRO West
General Vicente Alvarez St., Zone 4, Zamboanga City
Contact Nos. 0935-8609439

Zamboanga del Sur MSO

Pres. Corazon C. Aquino Regional Government,
Center, Balintawak, Pagadian City, Zamboanga del Sur
Contact Nos. 0907-2777422

REGION X:

Cagayan de Oro City MSO

Day Care Center Building, DENR-Compound,
Macabalan (Puntod), Cagayan de Oro City
Contact Nos. 0926-4148976

REGION XI:

Davao City MSO

Kilometer 7, SPED Road, Bangkal,
Davao City
Contact Nos. 0915-6127770

REGION XII:

Koronadal City MSO

DENR Region 12, Land Evaluation Party Office,
Aurora Street, Koronadal City, South Cotabato
Contact Nos. 0908-5459367, 0998-9840921

CARAGA Administrative Region:

CARAGA MSO

DENR Land Management Services Bldg.,
Ambago, Butuan City, Agusan del Norte
Contact Nos. (085) 342-6124, (085) 341-3250,
0948-620-9442, 0926-683-5521