



# PHILIPPINE NOTICES TO MARINERS

Monthly Edition No.: 2024-10  
31 October 2024

Notices Nos.: 102 to 110

---

## CONTENTS

- I Index of Charts Affected
  - II Chart Corrections
  - III Temporary & Preliminary Notices
  - IV List of Lights Corrections
  - V Coast Pilot Corrections
  - VI Navigational Warnings
  - VII Publication Notices
- 

Published by  
**National Mapping and Resource Information Authority**  
Lawton Avenue, Fort Bonifacio, Taguig City

ISSN 3028 -1067

Tel: (632) 8241-3494 to 98  
Email: [csu.hb@namria.gov.ph](mailto:csu.hb@namria.gov.ph) (NAMRIA Client Service Unit)  
Website: [www.namria.gov.ph](http://www.namria.gov.ph)

MARITIME AFFAIRS DIVISION  
Maritime Spatial and Safety Information Service  
Editorial Board 2024

*Editor-In-Chief:*  
**CDR LORENA JASMIN D LERIO**

*Supervising Editor:*  
**ENS GEORGE L DIMEN JR**

*Verifier:*  
**HERMIELYN C. SAGUCIO**

*Compilers:*  
**SN3 ANJANETTE A CRUCIS**  
**SN3 RHEAN MARK A MONILLA**  
**SN3 SAMUEL F SORIANO**  
**ROVILLA R. QUIMING**  
**TERESITA B. SARMIENTO**

**THE PHILIPPINE NOTICES TO MARINERS** is a monthly publication produced by the National Mapping and Resource Information Authority (NAMRIA). It contains the recent chart corrections, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained or by downloading at the NAMRIA website: <https://namria.gov.ph/downloads.aspx#publications> or by sending a request through the email address [maritime.affairs@namria.gov.ph](mailto:maritime.affairs@namria.gov.ph).

Organized chart corrections, cumulative and summary list of chart corrections as well as online hydrographic note are also available through the **Online Maritime Safety Information System (OMSIS)**, <https://isportal.namria.gov.ph/OMSIS/Default.aspx>

Masters of vessels and other concerned parties are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots, which may come to their attention, to the **Director, Hydrography Branch**. If such information warrants urgent attention, for instance the non-existence of aids to navigation or failure of light beacons or similar structures or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:


Mail	NAMRIA Hydrography Branch, 421 Barraca St San Nicolas, 1010 Manila, Philippines
E-mail	<a href="mailto:maritime.affairs@namria.gov.ph">maritime.affairs@namria.gov.ph</a>
Landline	(+632) 8245-0295
Online	<a href="https://namria.gov.ph/omsis/HNote10.aspx">https://namria.gov.ph/omsis/HNote10.aspx</a>

Active navigational warnings are accessible at <https://staging.geoportal.gov.ph/nwapp/>

## EXPLANATORY NOTES

1. The Philippine Notices to Mariners is divided into the following sections:

**Section I. Index of Charts Affected** – Contains the list of all nautical charts which have been affected by Notices to Mariners and the Notice Numbers which have affected them.



**Section II. Chart Corrections** - Contains corrections to nautical charts in sequential numbers with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:

Notice No. preceded by an asterisk “ \* ” indicates that the information is based upon the original Philippine source.

**Section III. Temporary & Preliminary Notices** – Contains Notices to Mariners that temporarily affect the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “preliminary” or “temporary”, respectively.

A list of Temporary and Preliminary Notices that are still in force, as well as those that are canceled, is published in this publication every month. The list may be read on page v.

**Section IV. List of Lights Corrections** – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contain updates will be denoted by an asterisk “ \* ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be printed, cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from True North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance, and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should also be forwarded to the Commandant of the Philippine Coast Guard.

**Section V. Coast Pilot Corrections** – Contains the corrections to the latest editions of the Philippine Coast Pilot books.

**Section VI. Navigational Warnings** – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

**Section VII. Publication Notices** – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of the safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard the ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed, especially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of the information, such satellite-derived positions may be more accurate than charted details.

## **List of Temporary and Preliminary Notices**

(in force as of 31 October 2024)

- 10(110)T/24 LUZON, W. Coast, Manila Bay – Wreck. Restricted Area
- 10(109)T/24 LUZON, W. Coast, Manila Bay - Buoy
- 10(108)T/24 DAVAO, NE. Coast, Pakiputan Strait - Buoys
- 09(101)P/24 LUZON, W. Coast, Zambales – Dredging
- 09(100)P/24 LUZON, W. Coast, Manila Bay – Reclamation
- 08(092)T/24 WEST PHILIPPINE SEA, Julian Felipe Reef - Buoys
- 08(091)T/24 LUZON, S. Coast, Odiongan Bay - Buoy
- 08(090)T/24 LEYTE, S. Coast, San Juan - Lights
- 08(089)T/24 LEYTE, N. Coast, Biliran I – Light
- 08(088)T/24 SAMAR, W. Coast, - Lights
- 08(087)T/24 SAMAR, NE. Coast, Hiuinatungan I - Light
- 08(086)T/24 KALAYAAN ISLAND GROUP, Pag-asa Island – Buoy
- 07(074)T/24 PALAWAN, N. COAST, Cabuli I. - Light
- 07(073)T/24 LUZON, S. COAST, Sibuyan I - Lights
- 07(072)T/24 LUZON, NE. COAST - Lights
- 07(071)T/24 PHILIPPINE RISE, Benham Bank - Buoys
- 07(070)T/24 PALAWAN, N. COAST, Coron Passage - Buoys
- 07(069)T/24 LUZON, S. COAST, Sibuyan Island - Lights
- 07(068)T/24 LUZON, S. COAST, Laguna de Bay - Lights
- 07(067)T/24 LUZON, N. COAST, Batan Island-Light
- 07(066)T/24 LUZON, W. COAST, Manila Bay – Anchorage
- 07(065)T/24 LUZON, NE. COAST, Padsan River - Dredging
- 09(114)P/23 LUZON. S. COAST, Batangas Bay - Terminal
- 03(048)T/23 PALAWAN, E. COAST, off Miniloc island - Buoy
- 03(047)T/23 BOHOL, W. COAST, Dawahon Bank – Light
- 02(032)T/23 PALAWAN, N. COAST, Coron Bay – Buoy
- 02(031)T/23 LUZON, W. COAST, Manila Bay – Buoy
- 01(020)T/23 LUZON, W. COAST, Manila Bay - Buoy
- 12(077)T/22 MASBATE, NORTH COAST, Masbate Harbor - Beacon
- 09(040)T/22 LUZON, W. COAST, Manila Bay – Buoy
- 07(032)T/22 LUZON, W. COAST, Manila Bay – Buoy
- 07(031)T/22 LUZON, W. COAST, Manila Bay – Buoy
- 05(022)T/22 LUZON, W. COAST, Manila Bay – Buoy
- 02(006)T/22 LUZON, W. COAST, Manila Bay – Buoys
- 04(023)P/19 MINDANAO,N. COAST, Iligan Bay – Buoy
- 02(014)P/17 MINDANAO,N. COAST, Butuan Bay – Submarine Pipeline

## **TABLE OF CONTENTS**

Index of Charts Affected - - - - -	01
Chart Corrections - - - - -	02
Temporary & Preliminary Notices - - - - -	06
List of Lights Corrections - - - - -	07
Coast Pilot Corrections - - - - -	08
Navigational Warnings - - - - -	09
Publication Notices - - - - -	12

## INDEX OF CHARTS AFFECTED

<b>Chart No</b>	<b>Notice No.</b>	<b>Chart No</b>	<b>Notice No.</b>	<b>Chart No</b>	<b>Notice No.</b>	<b>Chart No</b>	<b>Notice No.</b>
1501	10(109)T/24 10(110)T/24	4243	10(108)T/24	4708	10(102)24 10(104)24 10(108)T/24	PH2CMN40	10(104)24 10(106)24 10(108)T/24
1523	10(104)24 10(108)T/24	4250	10(110)T/24	4718	10(102)24	PH2NLZ40	10(109)T/24 10(110)T/24
1532	10(105)24	4624	10(104)24 10(108)T/24	4723A	10(103)24 10(107)24	PH2CVZ40	10(102)24
1534	10(106)24	4656	10(104)24 10(108)T24	4723B	10(103)24 10(105)24 10(107)24	PH2KIG40	10(103)24
1545	10(102)24	4706	10(102)24	5008	10(105)24	PH2SSA40	10(107)24
1550	10(102)24	4707	10(102)24 10(105)24 10(107)24	5010	10(105)24	PH4MCT40	10(109)T/24
1561	10(107)24					PH4CORG1	10(110)T/24
						PH5MHR40	10(109)T/24

II  
CHART CORRECTIONS

**\*10(102)24 – PANAY, SW. COAST, Antique - Legend**

Chart 1545 1Ed 02/02/2012 [WGS-84 DATUM] Last NM 09(103)23

Amend legend, from Dao to Tobias Fornier at 10°30.94'N 121°56.87'E

Chart 1550 1Ed 09/10/2020 [WGS-84 DATUM] Last NM 06(046)24

Amend legend, from Dao to Tobias Fornier at 10°30.94'N 121°56.87'E

Chart 4415 1Ed 31/03/58 Rev 27/02/89 [Luzon Datum] Last NM 07(086)23

Amend legend, from Dao to Tobias Fornier at 10°30.96'N 121°56.87'E

Chart 4706 2Ed 12/2010 [WGS-84 DATUM] Last NM 09(099)24

Amend legend, from Dao to Tobias Fornier at 10°31.1'N 121°56.8'E

Chart 4707 2Ed 11/2010 [WGS-84 DATUM] Last NM 09(098)24

Amend legend, from Dao to Tobias Fornier at 10°31.3'N 121°57.7'E

Chart 4708 2Ed 11/2010 [WGS-84 DATUM] Last NM 08(085)24

Amend legend, from Dao to Tobias Fornier at 10°31.4'N 121°57.6'E

Chart 4718 1Ed 10/16/1971 Rev 11/24/1975 [Luzon Datum] Last NM 08(083)24

Amend legend, from Dao to Tobias Fornier at 10°30.5'N 121°57.1'E

ENC Affected: PH2CVZ40

(Philippine Statistics Authority)

**\*10(103)24 – KALAYAAN ISLAND GROUP, Panata Island - Light**

Chart 4723A 2Ed 12/22/2018 [WGS-84 DATUM] Last NM 09(098)24

Amend characteristics of Panata Light from Fl(2)10s to Fl.10s

at 10°43.7'N 114°21.1' E

Chart 4723B 2Ed 20/04/2023 [WGS-84 DATUM] Last NM 09(098)24

Amend characteristics of Panata Light from Fl(2)10s to Fl.10s

at 10°43.7'N 114°21.1' E

ENC Affected: PH2KIG40

(Philippine Coast Guard)

**\*10(104)24 – MINDANAO, SE Coast, Davao Gulf, Pakiputan Strait – Light**

Chart 1523 1Ed 06/28/2017 [WGS-84 DATUM] Last NM 09(097)24

Amend characteristics of Panacan Light from Fl.G.10s18M to Fl.G.5s18M

at 07°09.17'N 125°39.76' E.

Chart 4624 2Ed 12/02/1991 [Luzon Datum] Last NM 03(021)24

Amend characteristics of Panacan Light from Fl.G.10s18M to Fl.G.5s18M

at 07°09.26'N 125°39.67'E.

# II CHART CORRECTIONS

## \*10(104)24 – MINDANAO, SE Coast, Davao Gulf, Pakiputan Strait – Light

(continued)

Chart 4656 1Ed 02/16/1933 Rev 09/08/1975 [Luzon Datum] Last NM 03(021)24

Amend characteristics of Panacan Light from Fl.G.10s18M to Fl.G.5s18M

at 07°09'15.4"N 125°39'40.3"E.

Chart 4708 2Ed 11/2010 [WGS-84 Datum] Last NM 10(102)24

Amend characteristics of Panacan Light from Fl.G.10s18M to Fl.G.5s18M

at 07°09.2'N 125°39.8"E.

ENC Affected: PH2CMN40  
(Philippine Coast Guard)

## 10(105)24 – NORTH BORNEO, E. COAST, Dent Haven – Depths

Chart 1532 1Ed 11/29/2019 [WGS-84 DATUM] Last NM 08(078)24

Insert



at 05°16.61'N 119°18.79' E

Chart 4707 2Ed 11/2010 [WGS-84 DATUM] Last NM 10(102)24

Insert



at 05°16.6'N 119°18.8'E

Chart 4723B 2Ed 20/04/2023 [WGS-84 DATUM] Last NM 10(103)24

Delete



at 12°16.6'N 119°18.8'E

Chart 5008 1Ed 02/15/2024 [WGS-84 DATUM] Last NM 04(029)24

Delete



at 12°16.6'N 119°18.8'E

Chart 5010 1Ed 06/30/2022 [WGS-84 DATUM] Last NM 08(078)24

Insert



at 05°16.6'N 119°18.8'E

ENC Affected: PH2CVZ40  
(UKHO)

## \*10(106)24 – DIPOLLO TO ZAMBOANGA, Sindangan Bay – Submarine cable

Chart 1534 1Ed 06/30/2024 [WGS84 Datum]

Insert



joining

08°34.78'N 123°05.05'E  
08°33.21'N 123°01.64'E  
08°30.00'N 122°58.53'E  
08°22.67'N 122°54.29'E  
08°20.41'N 122°51.90'E  
08°16.34'N 122°50.31'E  
08°12.81'N 122°48.16'E  
08°09.49'N 122°45.70'E  
08°08.73'N 122°44.48'E  
08°07.31'N 122°41.04'E

II  
CHART CORRECTIONS

\*10(106)24 – DIPOLOG TO ZAMBOANGA, Sindangan Bay – Submarine cable joining

(continued)

08°07.31'N 122°41.04'E  
08°09.62'N 122°41.48'E  
08°10.27'N 122°39.17'E  
08°09.44'N 122°36.93'E  
08°09.08'N 122°34.78'E  
08°09.33'N 122°32.95'E  
08°10.11'N 122°30.32'E  
08°09.64'N 122°26.88'E  
08°09.22'N 122°19.18'E  
08°07.84'N 122°16.05'E  
08°03.55'N 122°10.67'E  
07°57.03'N 122°07.06'E  
07°48.38'N 122°04.00'E

ENC's Affected: PH2CMN40  
(Owned by Globe, Eastern Telecom PI and Infinivan)

\*10(107)24 – PALAWAN W. Coast, Palawan Passage – Depth

Chart 1561 1Ed 11/29/2019 [WGS-84 DATUM] Last NM 02(004)24

Insert  Rep at 09°46.16'N 117°58.03'E

Chart 4707 2Ed 11/2010 [WGS-84 DATUM] Last NM 10(105)24

Insert  Rep at 09°46.2'N 117°58.0'E

Chart 4723A 2Ed 12/22/2018 [WGS-84 DATUM] Last NM 10(103)24

Insert  Rep at 09°46.2'N 117°58.0'E

Chart 4723B 2Ed 20/04/2023 [WGS-84 DATUM] Last NM 10(105)24

Insert  Rep at 09°46.2'N 117°58.0'E

ENC Affected: PH2SSA40  
(NAVMETOC)

# II CHART CORRECTIONS

**Note:** Erratum on Notice \*09(099)24 – corrected coordinates and light characteristics

**\*09(099)24 – LUZON, SE. COAST, Calantas Rock - Light**

Chart 1515 2Ed 08/30/2021 [WGS84 Datum] Last NM 08(082)24

Delete  Calantas Rock  
Fl.R.10s10m7M at 12°30.72'N 124°04.60'E

Chart 4264 1Ed 11/29/2019 [WGS84 Datum] Last NM 01(002)23

Delete  Calantas Rock  
Fl.R.10s10m7M at 12°30'43"N 124°04'36"E

Chart 4706 2Ed 11/2010 [WGS84 Datum] Last NM 09(098)24

Delete  Calantas Rock  
Fl.R.10s10m7M at 12° 30.7'N 124° 04.6'E

Chart 4715 1Ed 12/1958 Rev 07/1975 [Luzon Datum] Last NM 08(081)24

Delete  Calantas Rock  
Fl.R.10s10m7M at 12°30.61'N 124°04.65'E

Chart 4726A 4Ed 01/30/2018 [WGS84 Datum] 09(095)24

Delete  Calantas Rock  
Fl.R.10s10m7M at 12°30.7'N 124°04.6'E

Chart 5003 1Ed 13/02/2024 [WGS84 Datum] 08(079)24

Delete  Calantas Rock  
Fl.R.10s10m7M at 12°30.7'N 124°04.6'E

ENC Affected: PH2CVZ40  
(Philippine Coast Guard)

# III

## TEMPORARY AND PRELIMINARY NOTICES

### **\*10(108)T/24 – MINDANAO, SE Coast, Davao Gulf, Pakiputan Strait – Buoys**

1. Construction of a bridge is taking place in Pakiputan Strait.
2. The following lateral light-buoys have been established to mark the channel for navigation:

<b>Characteristics</b>	<b>Designation</b>	<b>Buoy Type</b>	<b>Position</b>
<i>Fl.G.3s</i>	<i>NB-1</i>	<i>Port</i>	7°06.17'N., 125°39.40'E.
<i>Fl.R.3s</i>	<i>NB-2</i>	<i>Starboard</i>	7°06.15'N., 125°39.51'E.
<i>Fl.G.3s</i>	<i>NB-3</i>	<i>Port</i>	7°05.80'N., 125°39.30'E.
<i>Fl.R.3s</i>	<i>NB-4</i>	<i>Starboard</i>	7°05.80'N., 125°39.44'E.

3. Mariners are advised to navigate with caution in the area.  
(WGS84 Datum)

Chart Affected: 1523, 4624, 4656, and 4708

ENC Affected: PH2CMN40  
(Philippine Coast Guard)

### **\*10(109)T/24 – LUZON, W. Coast, Manila Bay - Buoy**

A yellow spherical wave rider buoy with characteristics of Q(5)Y.10s was installed at 14° 32' 25.17"N., 120° 55' 36.36"E (WGS84 Datum).

Chart Affected: 1501, 4243  
ENC Affected: PH2NLZ40, PH4MCT40, PH5MHR40  
(Philippine Coast Guard)

### **\*10(110)T/24 – LUZON, W. Coast, Manila Bay – Wreck. Restricted Area**

1. A four (4) nautical mile radius exclusion zone has been established around the wreck at 14° 30.3' N., 120° 40.5' E.
2. No vessel shall navigate or remain within this exclusion zone, except those permitted by the Philippine Coast Guard.
3. Mariners are advised to navigate with caution in the area.  
(WGS84 Datum)

Chart Affected: 1501, 4250

ENC Affected: PH2NLZ40, PH4CORG1  
(Philippine Coast Guard)

# IV

## LIST OF LIGHTS CORRECTIONS

### LIGHTHOUSES

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERIST ICS (4)	Elev(m) (5)	Range (NM) (6)	STRUCTURE (7)	REMARKS (8)
<b>REGION IV-B - MIMAROPA</b>							
<b>MINDORO ORIENTAL</b>							
0158	F2551	DUYUGAN POINT	12 36 17.64 N 121 33 23.12 E	Fl(3)10s *		GRP	
<b>PALAWAN</b>							
0851	F2825.04	PANATA	10 43 42 N 114 21 07 E	Fl.10s *			TE 2023

Note: Asterisk (\*) indicates new information in the column above it

Positions given are approximate and in WGS84 Datum unless otherwise stated in column 8

V  
COAST PILOT CORRECTIONS

No Coast Pilot Correction for this month.

# VI

## NAVIGATIONAL WARNINGS

**See all active Navigational Warnings at  
<https://staging.geoportal.gov.ph/nwapp/>**

**NAVPHIL 065/24**

**MINDORO STRAIT.**

**AMNAY R, W.**

CHART 1552.

DREDGING AND SAND EXTRACTION IN PROGRESS IN AREA BOUNDED BY:

12-57.20N 120-43.71E

12-57.72N 120-46.15E

12-56.64N 120-46.25E

12-57.03N 120-46.88E

12-56.98N 120-46.96E

12-56.33N 120-46.34E

12-55.23N 120-46.74E

12-54.64N 120-44.35E.

**NAVPHIL 204/24**

**WEST PHILIPPINE SEA.**

**KALAYAAN ISLAND GROUP.**

CHART 4723A.

LIKAS ISLAND LIGHT 11-04.78N 115-01.33E,  
F2823.8, UNLIT.

**NAVPHIL 227/24**

**MANILA BAY.**

CHART 1501.

OIL SPILL RESPONSE OPERATIONS ONGOING. TEMPORARY EXCLUSION ZONE RADIUS FOUR MILES ESTABLISHED CENTERED ON 14-30.3N 120-40.5E. SHIPS ARE PROHIBITED FROM ENTERING OR REMAINING WITHIN THE ZONE. CONTACT PHILIPPINE COAST GUARD TO ENTER PROHIBITED AREA AND FOR UPDATED INFORMATION.

**NAVPHIL 266/24**

**TABLAS STRAIT.**

CHART 1543.

SOIL SAMPLING ACTIVITY IN PROGRESS BY BARGE MCRP 01, 843.00 TONS, AND MTUG ABIGAIL, 79.00 TONS, UNTIL 31 DEC 2024 IN AREAS BOUNDED BY:

A. 12-44.64N 121-30.29E

12-44.83N 121-30.71E

12-44.39N 121-31.88E

12-44.25N 121-31.33E

12-44.40N 121-31.10E.

B. 12-51.41N 121-29.61E

12-51.41N 121-30.03E

12-50.62N 121-30.06E

12-50.62N 121-29.70E.

CANCEL THIS MSG 01 JAN 25.

**NAVPHIL 272/24**

**SAMAR SEA.**

**CALBAYOG CITY.**

CHART 1539.

LIGHTBUOYS 12-02.58N 124-35.45E AND 12-03.35N 124-35.75E UNLIT.

**NAVPHIL 274/24**

**SAN MIGUEL BAY.**

CHART 1514.

SCIENTIFIC SURVEY BY MV ST ANTHONY EXPRESS 4, 35.00 TONS, BARGE LA ROCHE, 463.00 TONS, AND MTUG BELOY, 58.30 TONS, IN PROGRESS UNTIL 31 DEC IN AREA BOUNDED BY:

13-52.32N 123-04.15E

13-53.41N 123-17.16E

13-50.34N 123-18.90E

13-48.49N 123-19.43E

13-46.52N 123-17.88E

13-44.42N 123-15.18E

13-43.66N 123-11.18E

13-44.17N 123-07.04E

13-46.42N 123-02.90E

13-49.10N 123-02.96E.

CANCEL NAVPHIL 226/24.

CANCEL THIS MSG ON 01 JAN 25.

**NAVPHIL 293/24**

**BUTUAN BAY.**

**LA UNION PT, SW.**

CHART 1536.

SUBMERGED MOORING BUOY REPORTED 09-04.29N 125-31.05E.

**NAVPHIL 296/24**

**Luzon Strait and Philippine Sea.**

CHART 2200.

SUBMARINE CABLE REPAIR WORKS BY CS RESOLUTE, 12184 TONS, IN PROGRESS UNTIL 04 NOV IN AREAS BOUNDED BY:

A. 19-49.81N 123-54.03E

21-30.93N 126-29.46E

21-22.37N 126-36.05E

20-35.71N 125-38.29E

19-45.83N 124-12.52E

19-40.66N 123-59.82E.

B. 19-22.27N 120-22.15E

19-57.42N 121-18.61E

19-55.76N 121-38.43E

19-51.92N 121-48.41E

19-43.49N 121-42.08E

19-48.20N 121-30.06E

19-39.88N 121-15.54E

19-36.44N 121-02.22E

19-15.31N 120-27.03E.

CANCEL THIS MSG 05 NOV 24.

# VI

## NAVIGATIONAL WARNINGS

### **NAVPHIL 299/24.**

#### **LUZON SEA AND MANILA BAY.**

CHART 1501 AND 1502.

DREDGING AND RECLAMATION ACTIVITIES  
BY MV AN DA KANG 689, 5,445.00  
TONS, IN PROGRESS UNTIL 30 JUNE 2025 IN  
AREAS BOUNDED BY:

##### A. DREDGING AREA

15-02.55N 120-02.71E

15-02.56N 120-03.35E

15-01.76N 120-03.38E

15-01.76N 120-02.73E,

##### B. RECLAMATION AREA

14-33.23N 120-57.10E

14-33.28N 120-57.10E

14-33.24N 120-57.66E

14-33.23N 120-57.66E.

CANCEL THIS MSG 01 JULY 25.

07-06.27N 125-39.21E

07-06.21N 125-39.44E

07-05.97N 125-39.37E

07-06.04N 125-39.14E

07-06.12N 125-39.14E

07-06.16N 125-39.01E

B. 07-06.20N 125-39.49E

07-06.13N 125-39.72E

07-06.02N 125-39.75E

07-06.03N 125-39.83E

07-05.94N 125-39.86E

07-05.93N 125-39.75E

07-05.88N 125-39.70E

07-05.96N 125-39.42E.

CANCEL THIS MSG 26 NOV 24.

### **NAVPHIL 319/24**

#### **PHILIPPINE SEA.**

CHART 2200.

CABLE REPAIR BY PETER FABER, 2854

TONS, IN PROGRESS UNTIL 30 NOV

IN THE VICINITY OF THE ALONG LINE

JOINING:

05-29.73N 125 57.67E 05-30.72N 126 01.35E

05-32.81N 126 04.75E 05-40.09N 126 10.58E

05-42.25N 126 14.44E 05-44.94N 126 17.32E

05-45.66N 126 19.89E 05-47.68N 126 23.94E

05-49.37N 126 26.17E 05-51.61N 126 27.92E

05-53.41N 126 30.15E 05-56.82N 126 31.78E

06-00.43N 126 36.71E 06-04.90N 126 43.44E

06-14.78N 126 53.01E 06-26.98N 127 07.70E

06-30.52N 127 19.15E 06-30.54N 127 35.10E

06-35.91N 127 49.68E 06-35.93N 127 59.13E

06-39.23N 128 04.95E 06-45.05N 128 08.40E

07-04.40N 128 38.88E 07-05.64N 128 44.83E

07-08.71N 128 50.08E 07-14.16N 128 53.52E

07-28.37N 129 05.51E 07-32.42N 129 13.29E

07-37.78N 129 22.26E 07-41.82N 129 27.87E

07-55.86N 129 37.74E 08-00.39N 129 44.59E

08-10.86N 129 51.17E 08-12.78N 129 54.06E.

HALF MILE BERTH ADVISED.

CANCEL THIS MSG 01 DEC 24.

### **NAVPHIL 305/24**

#### **CALAMIAN GROUP.**

CORON PASSAGE.

CHART 1553.

PORT HAND LIGHTBUOY 11-59.30N 120-  
14.73E MISSING.

### **NAVPHIL 307/24**

#### **MANILA BAY.**

#### **MANILA SOUTH HARBOR.**

CHART 4243.

LIGHTBUOY, NNSL 8, 14-34.26N 120-54.64E  
OFF STATION TO 14-34.28N  
120-54.62E.

### **NAVPHIL 311/24**

#### **DAVAO GULF.**

#### **PAKIPUTAN STRAIT.**

CHART 1523.

BRIDGE CONSTRUCTION AND BORED  
PILLING WORKS BY XIN YU 28, 247 TONS,  
AND LU QIAO JIAN SHE ZHUANG 8, 2340  
TONS, IN PROGRESS UNTIL 25 NOV  
IN AREAS BOUNDED BY:  
A. 07-06.23N, 125-39.03E  
07-06.20N 125-39.16E

### **NAVPHIL 320/24**

#### **ILOILO STRAIT AND GUIMARAS STRAIT.**

CHART 1549.

GEOTECHNICAL INVESTIGATION BY MTUG  
ANA, 28.30 TONS, AND GALMAEGGI 2,  
0.78 TONS, IN PROGRESS UNTIL 31 JAN 25,  
ALONG LINES JOINING:

A. 10-46.69N 122-37.16E

10-46.32N 122-38.04E

10-46.25N 122-38.15E

10-46.06N 122-38.31E

10-45.01N 122-39.01E.

B. 10-35.69N 122-42.77E

10-35.34N 122-42.91E

10-35.03N 122-43.12E

10-34.21N 122-43.94E

# VI

## NAVIGATIONAL WARNINGS

10-33.81N 122-44.51E  
10-33.63N 122-44.95E  
10-33.10N 122-47.01E  
10-32.96N 122-47.44E  
10-32.81N 122-47.75E  
10-32.54N 122-48.14E  
10-32.09N 122-48.59E.  
CANCEL THIS MSG 01 FEB 25.  
CANCEL NAVPHIL 110/24 AND 159/24.

**NAVPHIL 321/24**  
**BASHI CHANNEL.**  
CHART 5001.  
CABLE LAYING OPERATIONS BY C/S  
DEPENDABLE, 12184 TONS, IN PROGRESS  
UNTIL FURTHER NOTICE IN AREA BOUNDED  
BY:  
20-45N 121-00E  
22-10N 121-00E  
22-10N 122-30E  
20-45N 122-30E.  
CANCEL NAVPHIL 158/24.

**NAVPHIL 323/24**  
**LINGAYEN GULF.**  
**ARINGAY PT, W.**  
CHART 1503.  
GUNNERY EXERCISES, 18 TO 22 NOV IN  
AREA BOUNDED BY:  
16-25.69N 120-08.10E  
16-25.77N 120-10.32E  
16-23.72N 120-10.39E  
16-23.67N 120-08.24E.  
CANCEL THIS MSG 23 NOV 24.

**NAVPHIL 333/24**  
**WEST PHILIPPINE SEA.**  
**PIEDRAS PT, NW.**  
CHART 1562.  
GUNNERY EXERCISES, 03 TO 10 NOV, IN  
AREA BOUNDED BY:  
10-18.38N 118-41.63E  
10-18.37N 118-44.68E  
10-15.35N 118-44.68E  
10-15.35N 118-41.63E  
CANCEL THIS MSG 11 NOV 24.

**NAVPHIL 334/24**  
**MINDANAO SEA.**  
**MANUK MANGKAW I, E.**  
CHART 1532.  
GUNNERY EXERCISES, 10 TO 16 NOV, IN  
AREA BOUNDED BY:  
4-49.22N 119-55.62E  
4-50.72N 119-58.15E  
4-48.89N 119-59.64E  
4-47.35N 119-57.07E.  
CANCEL THIS MSG 17 NOV 24.

**NAVPHIL 335/24**  
**CEBU-MACTAN CHANNEL.**  
CHART 4447.  
HYDROGRAPHIC SURVEY ACTIVITY, 01 NOV  
TO 30 DEC, IN AREA BOUNDED BY:  
10-19.63N 123-57.86E  
10-19.77N 123-58.06E  
10-19.60N 123-58.35E  
10-19.58N 123-58.18E  
10-19.53N 123-58.07E.  
CANCEL THIS MSG 01 JAN 25.

## VII

# PUBLICATION NOTICES

1. There is no publication notice for this month.
- 

## **NAMRIA BULLETIN**

1. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on Nautical charts and Nautical publications issued by this office, especially if this affects navigational safety in Philippine Waters. The information may be sent using the Hydrographic Note found on <https://namria.gov.ph/omsis/HNote10.aspx>.
2. Clients may purchase maps, nautical charts, publications and other maritime products online through <https://namria.gov.ph/eMapa>.
3. Please be advised that effective in October 2023, in alignment with Civil Service Commission Memorandum Circular numbers 22, series of 2014 and 6, series of 2022, and in support of the Department of Energy's energy-efficiency initiatives, we are implementing remote-work practice for non-frontline personnel every Friday. Frontline personnel engaged in critical functions and services will maintain their onsite presence.
4. Frontline personnel can be reached through the following contact numbers: Taguig City, Fort Bonifacio Map Sales Office (MSO) - (02) 8810-4831 to 42 at local 431, (02) 8810-5467, 0956 5587584, and 0915 2777903; San Nicolas, Manila MSO - (02) 8245-9498, (02) 8241-3494 at local 117, 0966 8523814, and 0921 3627524; DENR-Visayas Avenue (MSO) - 0999 6079193 and 0928 4497159; and Client Service Section - [css.gismb@namria.gov.ph](mailto:css.gismb@namria.gov.ph) and 02 88875466.

**Nautical Charts, Topographic Maps, Tide and Current Tables, and related publications are available for sale at the NAMRIA Map Sales Offices (MSO). Nautical Charts can also be purchased online thru <https://namria.gov.ph/eMapa/>**

Region	Address	MSO STAFF	Phone/Fax
Main	Lawton Avenue, Fort Andres Bonifacio, Taguig City	Michelle Ann M. Aguilar Ana Victoria A. Labor Marlon Y. Aguilar	(02) 8810-4831 to 42 loc 431 (02) 8810-5467 0956 5587584 0915 2777903
NCR	421 Barraca Street, San Nicolas, Binondo, Manila	SN3 Marilou B. Cinco Romeo B. Brizuela Mary Jane M. Montano	(02) 8245-9498 (02) 8241-3494 loc 117 0966 8523814
NCR	FMB Building DENR Compound, Visayas Avenue, Quezon City	Sherry Ann S. Perez Glenn M. De Jesus	0999 6079193 0928 4497159
I	DENR Government Center, Sevilla City, San Fernando, La Union	<b>Temporarily Closed</b>	
II	DENR-Land Evaluation Party Building II, Brgy. Carig, Tuguegarao City	Rubilyn T. Pulpulaan	0917 6519625
III	DENR Compound, Diosdado, Macapagal Gov't. Center. Maipis City, San Fernando, Pampanga	Rosalina M. Libunao	0991 3509756
IVA	Provincial Planning and Development Office, Capitol Complex, Batangas City	Engr. Leda P. Velasquez	0961 4552583
IVB	DENR-PENRO Santa Monica, Puerto Princesa City	Juvy B. Sarmiento Corazon L. Zeñarosa	0916 203 8041
V	DENR-Operation/Survey Division, Rizal Street, Sagpon, Legaspi City, Albay	Isabelita T. Climaco	0906 3363033
VI	Manuel Lagunilla Bldg., DENR Compound, Parola, Iloilo City	<b>Temporarily Closed</b>	
VII	DENR-CENRO Building, Arellano Boulevard corner V. Sotto Street Pier 3, Cebu City	Melchor Togonon Renato B. Alcontin, Jr.	0922 7910372 0931 0010341 0961 4552579
VIII	DENR Compound, Santo Niño Extension, Tacloban City	<b>Temporarily Closed</b>	
IX	Pres. Corazon C. Aquino Regional Government Center, Balintawak, Pagadian City, Zamboanga Del Sur	Ednalyn C. Macahidhid	0955 5826075 0948 2943647
IX	DENR CENRO, West General Vicente Alvarez St., Zone 4, Zamboanga City	Annette P. Flores	0955 8928777
X	DENR Building Macabalan, Cagayan de Oro City, Misamis Oriental	<b>Temporarily Closed</b>	
XI	Kilometer 7, SPED Road, Bangkal, Davao City	<b>Temporarily Closed</b>	
XII	3rd Floor, DENR Building Land Evaluation Survey Section, Aurora Street, Barangay Zone IV Koronadal City, South Cotabato	Jeanyluz B. Bautista	0909 9324745
CARAGA	DENR - Land Management Services Building, Ambago, Butuan City, Agusan del Norte	Maricar E. Siega	0948 3619452