



PHILIPPINE NOTICES TO MARINERS

Edition No.: 06
30 June 2017

Notices Nos.: 034 to 036

CONTENTS

- I Index of Charts Affected
 - II Notices to Mariners
 - III Corrections to Nautical Publications
 - IV Navigational Warnings
 - V Publication Notices
-

Produced by the Hydrography Branch

Published by the
Department of Environment and Natural Resources
NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Notices to Mariners – Philippine edition are now on- line at
[http:// www.namria.gov.ph/download.php](http://www.namria.gov.ph/download.php)

Subscription may be requested thru e-mail at icsu-hd@namria.gov.ph

THE PHILIPPINE NOTICES TO MARINERS is the monthly publication produced by the Hydrography Branch of the National Mapping and Resource Information Authority (NAMRIA). It contains the recent charts correction data, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained by sending a request through e-mail address: oss@namria.gov.ph or by downloading at the NAMRIA website: www.namria.gov.ph/download.php.

Masters of vessels and other concerned are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots which may come to their attention to the **Director, Hydrography Branch**. If such information warrants urgent attention like for instance the non-existence of aids to navigation or failure of light beacons or similar structure or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:

Mail: NAMRIA-Hydrography Branch, 421 Barraca St., San Nicolas, 1010 Manila, Philippines

E-mail: oss@namria.gov.ph

Fax: (+632) 242-2090


The form at the back cover page of this publication must be used in reporting information on dangers to navigation, lighted aids, and other features that should be included in the nautical charts.

Explanatory Notes

- The Philippine Notices to Mariners is divided to following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts which have been affected by Notices to Mariners and the notice numbers which have affected them.

Section II-A. Notices to Mariners - Contains corrections to nautical charts in sequential number with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:



Notice No. preceded by asterisk “ * ” indicates that the information is based upon original Philippine source.

Section II-B. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affects the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “preliminary” or “temporary”, respectively.

Section III-A. Corrections to List of Lights – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contains updates will be denoted by an asterisk “ * ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from true the North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should be forwarded to the Commandant of the Philippine Coast Guard.

Section III-B. Coast Pilot Corrections – Contains the corrections to the latest edition of the Philippine Coast Pilot book.

Section IV. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section V. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard ship and use a lookout during navigation.
4. **WARNINGS:** Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some temporary lights. Buoys and beacons are sometimes lost or destroyed specially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of information, such satellite-derived positions may be more accurate than charted details.

Nautical Charts, Topographic Maps, Tide and Current Tables and related publications are available for sale at the following NAMRIA Map Sales Offices (MSO):

METRO MANILA:

NAMRIA Main Office MSO

Fort Andres Bonifacio, Taguig City
Contact Nos. (02) 810-4831 to 34 local 240,
(02) 810-5467, 0919-298990

Manila MSO

Hydrography Branch
421 Barraca Street, San Nicolas, Manila
Contact Nos. (02) 241-3494 to 96 local 117,
(02) 245-9498, 0919-6259276

DENR Central Office MSO

Forest Management Bureau (FMB) Compound
Visayas Avenue, Quezon City
Contact Nos. (02) 925-1157, 0915-5433557

REGION I:

San Fernando (La Union) MSO

DENR Government Center
Sevilla, San Fernando City
Contact Nos. (072) 700-7957, (072) 242-6201,
0927-9187175

REGION II:

Cagayan MSO

DENR – LEP, Building II
Carig, Tuguegarao City
Contact Nos. (072) 700-7957, (072) 242-6201,
0999-4086917

CORDILLERA ADMINISTRATIVE REGION:

Baguio City MSO

Cottage I Forester Compound,
PACDAL, Baguio City
Contact Nos. (074) 442-5429, (074) 442-4531,
0918-9203590

REGION III:

Nueva Ecija MSO

GIS Room, WMRC Building,
Central Luzon State University Compound
Maharlika Highway, Muñoz City
Contact Nos. (044) 456-0690, 0917-9313827

Pampanga MSO

Diosdado Macapagal Government Center
Maimpis, San Fernando City
Contact Nos. (045) 963-4650, (045) 963-4646 or 49,
0910-3725623

REGION IV-A:

Southern Tagalog MSO

Provincial Planning and Development Office
Laurel Park, Capitol Site, Batangas City
Contact Nos. (043) 723-3286, 0919-9750907

REGION IV-B:

Puerto Princesa MSO

DENR-PENRO Compound,
Brgy. Santa Monica, Puerto Princesa City
Contact Nos. (048) 433-5638, (048) 433-5639,
0928-7545363

REGION V:

Legazpi City MSO

DENR-Ecosystems Research and Dev't Service,
Kalikasan Park, Anahaw Vill., Sagpon, Legazpi City
Contact Nos. (052) 481-1515, (052) 481-1542,
(052) 480-9825, 0920-4378877

REGION VI:

Iloilo City MSO

DENR – Forestry Building,
Parola, Fort San Pedro, Iloilo City
Contact Nos. (033) 336-5480, (033) 336-1013,
0919-8873862

REGION VII:

Cebu City MSO

Room 301, Osmeña Bldg. II, Osmeña Blvd, Cebu City
Contact Nos. (032) 505-9945, 0932-6418592

REGION VIII:

Tacloban City MSO

DENR Compound, Sto. Niño Extension, Tacloban City
Contact Nos. (053) 325-6223, (053) 321-3386,
0921-3628489

REGION IX:

Zamboanga City MSO

DENR CENRO West
General Vicente Alvarez St., Zone 4, Zamboanga City
Contact Nos. (062) 991-2149, (062) 992-2484,
0935-8609439

Zamboanga del Sur MSO

4th floor Pantaran Building, Rizal Avenue,
Balingasan District, Pagadian City
Contact Nos. (062) 215-4065, 0907-2777422

REGION X:

Cagayan de Oro City MSO

Day Care Center Building, DENR-Compound,
Macabalan (Puntod), Cagayan de Oro City
Contact Nos. (088) 856-9050, (088) 856-9591,
0926-4148976

REGION XI:

Davao City MSO

FRCD Building, DENR-Compound
Lanang, Davao City
Contact Nos. (082) 234-4401, (082) 234-7441,
0915-6127770

REGION XII:

Koronadal City MSO

DENR Region 12, Land Evaluation Party Office,
Aurora Street, Koronadal City, South Cotabato
Contact Nos. (083) 228-8476, 0908-5459367,
0998-9840921

REGION XII:

Butuan City MSO

Day Care Center Building, DENR Compound,
Ambago, Butuan City, Agusan del Norte
Contact Nos. (085) 342-6124, (085) 341-3250,
0948-6209442, 0926-6835521

TABLE OF CONTENTS

Index of Charts Affected	1
Notices to Mariners	2
Temporary & Preliminary Notices	
List of Lights Corrections	4
Coast Pilot Corrections	
Navigational Warnings	5
Publication Notices	12

I**INDEX OF CHARTS AFFECTED**

Charts No.	Notices Nos.		Charts No.	Notices Nos.
1535	06(034)17		4255	06(035)17
1542	06(035)17		4272	06(035)17
1543	06(035)17		4453	06(035)17
4211	06(035)17		4604	06(034)17
4212	06(036)17		4708	06(034)17
4218	06(035)17			

II NOTICES TO MARINERS

***06(034)17 – MINDANAO, N Coast, Sinacaban – Light**

Chart 1535 1Ed 02/02/2012 [WGS-84 Datum] Last NM 05(025)17

AMEND characteristics of Sinonoc Light from Fl(3)10s to Fl.4s at:
08° 18.02' N., 123° 51.88' E.

Chart 4604 1Ed 04/30/1956 Rev 01/07/1985 [WGS-84 Datum] Last NM 07(154)16

AMEND characteristics of Sinonoc Light from Fl(3)10s to Fl.4s at:
08° 18.10' N., 123° 51..80' E.

Note: Cancel Notice No. 09(204)T/16.
(PCG NM No. 098 of 2017; HD 101/17)

***06(035)17 – MARINDUQUE I., NW. COAST, Port Balanacan – Wreck**

Chart 1542 1Ed 02/02/2012 Rev 07/31/2012 [WGS-84 Datum] Last NM 04(018)17

INSERT Wreck  *Wk* at: 13° 31.55' N., 121° 51.44' E.

INSERT Wreck  *Wk* at: 13° 31.60' N., 121° 51.47' E.

Chart 1543 1Ed 02/02/2012 [WGS-84 Datum] Last NM 09(202)16

INSERT Wreck  *Wk* at: 13° 31.55' N., 121° 51.44' E.

INSERT Wreck  *Wk* at: 13° 31.60' N., 121° 51.47' E.

Chart 4218 1Ed 03/1958 [Luzon Datum] Last NM 05(032)17

INSERT Wreck  *Wk* at: 13° 31.64' N., 121° 51.36' E.

INSERT Wreck  *Wk* at: 13° 31.69' N., 121° 51.39' E.

Continued to the next page

II NOTICES TO MARINERS

Chart 4272 1Ed 02/19/1962 Rev 02/28/1977 [Luzon Datum] Last NM 02(013)16

INSERT Wreck  *Wk* at: 13° 31.64' N., 121° 51.36' E.

INSERT Wreck  *Wk* at: 13° 31.69' N., 121° 51.39' E.

Chart 4453 1Ed 01/05/1959 Rev 07/21/1975 [Luzon Datum] Last NM 09(219)15

INSERT Wreck  *Wk* at: 13° 31' 38.1"N., 121° 51' 21.6"E.

INSERT Wreck  *Wk* at: 13° 31' 41.3"N., 121° 51' 23.1"E.

NOTE: This cancels Notice No. 04(054)13 Item No. 2.
(NAMRIA Research Report; HD 108/17)

***06(036)17 – LUZON, W. COAST, Subic Bay – Buoy**

Chart 4211 1Ed 06/20/1960 Rev 01/12/1981 [Luzon Datum] Last NM 01(005)17

DELETE Agusuhin Point Lighted Buoy  at: 14° 48.41' N., 120° 12.95' E.

Chart 4212 1Ed 03/07/2005 [WGS-84 Datum] Last NM 09(214)16

DELETE Agusuhin Point Lighted Buoy  "7"
 *G* at: 14° 48.32' N., 120° 13.04' E.

Chart 4255 2Ed 01/06/1975 Rev 06/17/1985 [Luzon Datum] Last NM 04(021)17

DELETE Agusuhin Point Lighted Buoy  at: 14° 48.41' N., 120° 12.95' E

(SBMA Email; HD 115/17)

III

LIST OF LIGHTS CORRECTIONS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range(NM) (6)	STRUCTURE (7)	REMARKS (8)
REGION III – CENTRAL LUZON							
ZAMBALES							
0724	<i>Agusuhin Point Lighted Buoy</i>						DELETED From the List of Lights 6/17
REGION X – NORTHERN MINDANAO							
MISAMIS OCCIDENTAL							
0501	F2275.5	SINONOC	08 18 06 N 123 51 48 E	FI W 4s			6/17 *

Note: Asterisk “*” indicates new information in the column above it.

IV

NAVIGATIONAL WARNINGS

Date: 26 April 2017

Reference: PCG NTM 072-2017 (HD 078/17)

MESSAGE

NAVPHIL 045/17 – LUZON E. COAST, MANILA BAY – BATHYMETRIC SURVEY

EGS ASIA INC. WILL CONDUCT BATHYMETRIC SURVEY AND METOCEAN STUDY ON 25 APRIL TO 15 JUNE 2017 FOR CAVITEX RECLAMATION PROJECT AT BACOR, CAVITE OR ON AREAS BOUNDED BY THE FOLLOWING COORDINATES:

POINT 1	14° 28' 53.32" N.	120° 55' 19.22" E.
POINT 2	14° 28' 35.70" N.	120° 54' 59.43" E.
POINT 3	14° 28' 04.18" N.	120° 55' 07.57" E.
POINT 4	14° 27' 40.62" N.	120° 55' 36.29" E.
POINT 5	14° 27' 47.95" N.	120° 56' 41.31" E.
POINT 6	14° 28' 16.39" N.	120° 57' 39.53" E.
POINT 7	14° 29' 25.50" N.	120° 57' 14.78" E.
POINT 8	14° 29' 13.31" N.	120° 55' 47.15" E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE-MENTIONED AREAS ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

IV NAVIGATIONAL WARNINGS

Date: 24 May 2017

Reference: PCG NTM 088-2017(HD 093/17)

MESSAGE

NAVPHIL 059/17 – LUZON, W. COAST, PASIG RIVER – MOORING DOLPHINS

THE OLYMPIC ENGINEERING AND SALES CORPORATION-UNIVERSAL ROBINA CORPORATION (OESC-URC) WILL BE INSTALLING SIX (6) SETS OF MOORING BREASTING DOLPHINS ALONG PASIG RIVER, BAGONG ILOG, PASIG CITY. INSTALLATION WILL BE FROM 08 MAY TO 31 JULY 2017 AT THIS POSITION;

14° 33' 40"N., 121° 03' 57"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV NAVIGATIONAL WARNINGS

Date: 25 May 2017

Reference: Proclamation No. 216 (HD 095/17)

MESSAGE

NAVPHIL 061/17 – MINDANAO ISLAND & SULU ARCHIPELAGO – SECURITY WARNING

THE PHILIPPINE GOVERNMENT RECENTLY PLACED THE WHOLE ISLAND OF MINDANAO AND THE SULU ARCHIPELAGO UNDER MARTIAL LAW DUE TO THE HOSTILITIES IN MARAWI CITY IN THE PROVINCE OF LANA DEL SUR.

ALL SHIPS/WATERCRAFTS TRANSITING IN THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES. MASTERS ARE REQUESTED TO REPORT TO THE PHILIPPINE COAST GUARD OR THE PHILIPPINE NAVY ANY SUSPICIOUS VESSELS OR ACTIVITIES IN THE ABOVE MENTIONED AREAS.

IV NAVIGATIONAL WARNINGS

Date: 09 June 2017

Reference: PCG NTM 099-2017 (HD 102/17)

MESSAGE

NAVPHIL 065/17-CEBU, E. COAST, MANDAUE, CEBU-REPAIR/REHABILITATION

THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAY (DPWH) IS CURRENTLY CONDUCTING REPAIR/REHABILITATION OF PIER FOOTING NUMBER 7 AND PIER FOOTING NUMBER 8 OF OLD MANDAUE-MACTAN BRIDGE WHICH STARTED LAST 10 MAY 2017 AND IS ESTIMATED TO BE COMPLETED BY DECEMBER 2018. THE REPAIR ACTIVITIES WILL BE CONDUCTED AT THE FOLLOWING COORDINATES:

BRIDGE PIER FOOTING NO. 7	10° 19' 13"N., 123° 57' 19"E.
BRIDGE PIER FOOTING NO. 8	10° 19' 09"N., 123° 57' 21"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

IV NAVIGATIONAL WARNINGS

Date: 13 June 2017

Reference: PCG NTM 101-2017 (HD 104/17)

MESSAGE

NAVPHIL 067/17 – ITBAYAT, NW. COAST, ITBAYAT, BATANES – CABLE RECOVERY

THE VESSEL “C/S DECISIVE” WILL CONDUCT CABLE RECOVERY – C2C SEGMENT 2C LOCATED AT NORTHWEST OF ITBAYAT, BATANES ON 15 JUNE 2017 TO 14 JULY 2017 THE LIMIT OF THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A	20° 42.6563' N., 121° 32.2529' E.
POINT B	20° 52.1447' N., 121° 35.4658' E.
POINT C	21° 12.1580' N., 121° 44.3534' E.
POINT D	21° 09.0313' N., 121° 50.4179' E.
POINT E	20° 47.6672' N., 121° 43.9282' E.
POINT F	20° 39.0882' N., 121° 31.3522' E.
POINT R5	20° 42.6160' N., 121° 28.9300' E.
POINT R6	21° 08.9410' N., 121° 46.5020' E.

ALL SHIPS/WATERCRAFTS TRANSITING IN THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO OBSERVE SAFE DISTANCE FROM THE VESSEL AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

IV NAVIGATIONAL WARNINGS

Date: 27 June 2017

Reference: PCG NTM 109-2017 (HD 112/17)

MESSAGE

NAVPHIL 073/17 – CEBU, E. COAST, CEBU CITY – NO SAIL ZONE

THE PHILIPPINE COAST GUARD WILL ENFORCE A “NO SAIL ZONE” DUE TO THE ASEAN 2017 EVENT THAT WILL BE HELD AT RADISSON BLU HOTEL, CEBU CITY ON 29 JUNE TO 08 JULY 2017, IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

**POINT A: 10° 18' 37.45"N., 123° 55' 33.03"E.
POINT B: 10° 18' 26.13"N., 123° 55' 42.66"E.
POINT C: 10° 18' 07.93"N., 123° 55' 19.61"E.
POINT D: 10° 18' 19.05"N., 123° 55' 09.34"E.**

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

IV NAVIGATIONAL WARNINGS

Date: 27 June 2017

Reference: PCG NTM 111-2017 (HD 114/17)

MESSAGE

NAVPHIL 074/17 – MACTAN IS., NE. COAST – WATER ACTIVITY

THE COBRA IRONMAN 70.3 PHILIPPINES TRIATHLON RACE 2017 WILL BE HELD ON 05 TO 06 AUGUST 2017 FROM 6AM TO 9AM ALONG THE VICINITY WATERS OFF SHANGRILA MACTAN BEACH RESORT, LAPU-LAPU CITY, CEBU OR IN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

POINT A	10° 18' 22.01"N., 124° 01' 16.86"E.
POINT B	10° 18' 20.54"N., 124° 01' 19.80"E.
POINT C	10° 18' 31.55"N., 124° 01' 26.75"E.
POINT D	10° 18' 30.79"N., 124° 01' 28.02"E.
POINT E	10° 18' 07.24"N., 124° 01' 13.35"E.
POINT F	10° 18' 08.06"N., 124° 01' 11.92"E.
POINT G	10° 18' 08.21"N., 124° 01' 18.23"E.
POINT H	10° 18' 19.75"N., 124° 01' 15.55"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

V

PUBLICATION NOTICES

1. Correction

The Publication Notice published in the May 2017 Edition of the Philippine Notices to Mariners should read as follows:

Chart 1548 – Southern Part of Tañon Strait and Cebu Strait to Bohol Sea
Scale 1:150,000, 1st Edition, 17 May 2017

Call the NAMRIA Map Sales Office (MSO) – Manila Branch at telephone number (+632) 241-3494 local 117 for details regarding the purchase of the abovementioned nautical charts.

REQUEST FOR CORRECTIVE INFORMATION

Mariners are requested to notify the **Hydrography Branch, NAMRIA** of any changes or discrepancies found on Charts published by this office especially if this affect navigational safety in Philippine Waters. Reports may be sent by facsimile (FAX No. (632) 242 20 90) or by speed mail to:

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY
Hydrography Branch
421 Barraca Street, San Nicolas
1010 Manila, Philippines
Attention: Maritime Affairs Division

Reports may also be sent by electronic mail (e-mail) to:

maritime.affairs@namria.gov.ph

(Please send the information in format similar to that found at the back cover of this publication)

REPORT OF SIGHTING/DISCOVERY

General locality _____

Date _____ Time _____

Approximate Position: Latitude. _____ N.,

Longitude. _____ E.

Reference datum: _____

Position Determined by (Method/Instrument used):

Nature/description of MSI (*Floating hazard, unlit light station, uncharted shoals, adrift vessels etc.*)

Weather/sea condition in the locality _____

MSI Reported by:

Master or Navigator

Vessels/Country Registry

Enroute to: _____

To: The Director
Hydrography Branch
421 Barraca Street, San Nicolas
1010 Manila, PHILIPPINES
Fax No. (632) 242-20-90
E-mail: icsu_hd@namria.gov.ph